

PRODUCT SPECIFICATION SHEET



WYNN'S® Power Steering Fluid Service Kits



Power Steering Fluid degrades over time and mileage as it is subjected to extreme heat and pressure.

- Degraded fluid can cause:
 - Power steering system noise.
 - Decreased steering performance, especially on cold starts.
 - Decreased life of power steering components.
- Wynn's® Power Steering Flush is formulated to:
 - Remove harmful power steering system deposits and impurities.
- Wynn's Power Steering Fluid & Conditioner is formulated to:
 - Restore power steering system performance.
 - Condition and revitalize power steering system seals.
 - Reduce wear and noise.
 - Help postpone or eliminate the need to replace power steering components.
 - Help prevent internal power steering fluid leakage from developing.
 - Help extend the life of power steering components.
- Wynn's Power Steering Fluid & Conditioner is available in three types.
 1. Conventional Power Steering Fluid base.
 2. ATF base.
 3. Type H/A (for Honda and Acura).

Power Steering Fluid Service Kits

Part #10017	4 x 2-Part Kit (11 oz. #62409 Power Steering Flush + 64 oz. #61904 Power Steering Fluid & Conditioner) per case
Part #10019	4 x 2-Part Kit (11 oz. #62409 Power Steering Flush + 64 oz. #57806 Power Steering Fluid & Conditioner) per case
Part #10022	4 x 2-Part Kit (11 oz. #62409 Power Steering Flush + 64 oz. #39601 Power Steering Fluid & Conditioner) per case



PROFESSIONAL PRODUCTS

WYNN OIL COMPANY 1050 W. Fifth Street • Azusa, CA 91702

626-334-0231

www.wynnsusa.com



Wynn's® Power Steering Fluid Service Kits

THE PROBLEM

Power steering fluid is a hydrocarbon based fluid, similar to other automotive fluids like motor oil, automatic transmission fluid and gear oil. Like these fluids, its performance degrades over time. Power steering fluid operates under high pressures and temperatures, which can cause the fluid to break down and lose its protective lubricating properties, resulting in excessive component wear, noise and hard steering.

The first sign of problems in a vehicle's power steering system is often unusual or excessive noise or sluggish steering, especially shortly after the vehicle is started. This is especially noticeable in cold weather and has come to be known as "Morning Sickness." This is due to the degraded fluid being very viscous at low temperatures and power steering system seals being especially hard at low temperatures, with both factors contributing to hard steering.

Often power steering fluid is only changed when the power steering unit is replaced, as the fluid change process is tedious and time consuming. If the fluid could be easily changed on a routine basis, many of the problems associated with degraded fluid and premature component wear could be prevented.

THE SOLUTION

A Wynn's® Power Steering Flush service is designed to flush out the old dirty fluid and contaminants from the system and replace it with clean, new power steering fluid easily and cost effectively. Wynn's Power Steering Flush Kits are designed to be used with Wynn's Power Steering Flush Machines (P/N 22000 and P/N 23000). Check the Recommendations Chart included with these machines for the proper kit for each vehicle being serviced.

A Wynn's Power Steering Flush service is designed to:

- Help stop hard steering, especially on cold starts.
- Remove deposits and impurities from the power steering system.
- Condition and revitalize seals.
- Reduce power steering wear and noise.

When a Wynn's Power Steering Flush service is performed as a preventative maintenance measure, it helps to extend the life of the power steering unit, pump and seals.

Wynn's Power Steering Flush Kits containing 32 oz. of Power Steering Flush and 32 oz. of Power Steering Fluid & Conditioner are also available (P/N's 10179, 10176 and 11001). The use of these larger volume kits is recommended where a greater fluid exchange efficiency is needed than would be achieved using the smaller volume kits described here.

CAUTION: If the power steering system is leaking badly, mechanical repairs may be necessary and this procedure is not recommended.



CERTIFICATE #A3958

WYNN'S
Azusa, California 91702
© 2005 Illinois Tool Works Inc.
www.wynnsusa.com

08/03

Item No. 9M4283